## Verified Operation of Our Software & Devices for Weighing Products with Windows 7 (32-bit Version)

		Updated: January 2010
Description		Results
WinCT Ver.3.00	RsCom	Verified
	RsKey	$\mathbf{Failed}^{i}$
	RsWeight	Verified
WinCT Ver.4.01	RsCom	Verified
	RsKey	Verified <sup>ii</sup>
	RsWeight	Not available <sup>iii</sup>
WinCT-Moisture Ver.2.41	RsFig	Verified
	RsTemp	Verified
WinCT-Viscosity Ver.1.11	RsVisco	Verified
WinCT-Plus Ver.2.10	RsMulti	Verified <sup>iv</sup>
	DeviceInstaller	Verified
	Com Redirector	Verified
WinCT-AD4212C Ver.1.02		Verified
WinCT-Pipette Ver.1.1.4		Verified
AD-1688		Verified
AD-8527		Verified
OP-02 (Quick USB)		Verified
AX-USB-xx (Serial/USB converter)		Verified <sup>v</sup>

 $^{i}$  Data cannot be transferred.

 $<sup>^{\</sup>rm ii}\,$  The data transfer rate was slower compared with Windows Vista/XP.

Windows Vista/XP:	Approx. 6.3 times/sec.
Windows 7:	Approx. 1.4 times/sec.

<sup>iii</sup> Please use the version 3.00 should this function be required.

<sup>iv</sup> As with Windows Vista, Excel cannot be started from RsMulti.

v Please use the driver software for Windows Vista.