



o Wide-range temperature and humidity measurement accuracy

- Measurement accuracy for temperatures of 0 to 60°C and humidity of 0 to 100% are listed in the graph below.

1) Measurement accuracy (Temperature)



2) Measurement accuracy (Humidity)



3) Measurement accuracy (Barometric pressure)

±3 h Pa (0 to 60°C)

4) Measurement accuracy (Vibration)

±20% (Static acceleration)