

GUI screen allowing intuitive operation

Continuous feeding control mode menu screen



Batch feeding control mode menu screen



Continuous feeding control mode operation screen

Feeder number

Start/Stop control button

Gross weight indicator

Accumulation value indicator

Flow rate indicator

Target flow rate setting box

Manipulative variable indicator

MV manual setting button

To display the trend graph screen

To display the feeder limit setting screen

Feeder 1-4 display selection


To display the continuous feeding setting screen

Batch feeding control mode operation screen


Net weight indicator

Target weight setting box

Trend graph screen



Auto tuning screen



Feeders 1 – 4 operation screens



Continuous/Batch feeding control selection screen

